

## INTRODUCTION

- Misaligned or missing tie bars are commonly seen in newly constructed PCC pavements
- Effects of misaligned or missing tie bars are unknown
- Previous research suggests that they could be a contributing factor to longitudinal joint distresses



Source: Mallela, J. (2011). Evaluation of Longitudinal Joint Tie Bar System. Denver, CO: Colorado Department of Transportation.

- Conduct a comprehensive literature review on the design and performance of longitudinal joints with tie bars
- Perform experimental testing and analytical modeling to determine the effects misplaced tie bars have on the longitudinal joint
- Develop tie bar placement tolerances for the South Dakota DOT to implement

## South Dakota DOT Specifications

Type: # 5, Grade 40/60, Epoxy Coated, Deformed Bar

Length:


- 30" if Installed in Fresh Concrete
- 24" if Installed in Hardened Concrete

Spacing:





- 48" C-C for Sawed or Construction Joints w/ Keyway
- 30" C-C for Construction Joints without Keyway

Placement:

- Mid-depth of the slab
- Perpendicular to the joint
- Parallel to the ground
- Half of the tie bar is embedded on each side of the joint




## Testing Matrix

MISALIGNMENT TYPE	MISALIGNMENT MAGNITUDE	MISALIGNMENT TYPE	MISALIGNMENT MAGNITUDE
Vertical Translation: 	X = 1 inches	Longitudinal Translation: 	X = 3 inches
	X = 2 inches		X = 5 inches
	X = 3 inches		X = 7 inches
	X = 4 inches		X = 9 inches
Vertical Skew: 	X = 2 inches	Horizontal Skew: 	X = 16 inches
	X = 4 inches		X = 20 inches
	X = 6 inches		X = 24 inches
	X = 8 inches		X = 28 inches

Experimental Testing Result Summary:


- Vertical Translation: Results were similar to the Aligned Specimens.
- Vertical Skew: Found a slight increase in the Joint Faulting.
- Longitudinal Translation: Results were identical to the Aligned Specimens.
- Horizontal Skew: Effected the Actuator Load, Joint Opening, and Joint Faulting; Joint Opening exceeded 1/8 of an inch when the misalignment magnitude was 20 inches ( CRITICAL)




## Analytical Modeling

### MATERIALS:



- Concrete: Damaged Plasticity Model
- Tie Bar: Elastic Material Model (linear)



### CONCRETE STRESS DISTRIBUTIONS:




### TIE BAR STRESS DISTRIBUTIONS:



## TEST SPECIMEN INSTRUMENTATION

- Two - 24"x48"x10" concrete slabs connected by a 30" long, #5, Grade 60, epoxy coated tie bar
- Tie bar was installed with the various misalignment types and magnitudes specified in the test matrix
- Joint between slabs created by 1/8th inch thick acrylic sheet
- Strain gages were installed on the tie bar at the joint
- LVDT's measured displacement in all three directions



## CONCLUSIONS

- The Horizontal Skew misalignment type had the most significant effect on the actuator load and joint opening
- The misaligned tie bars performed adequately within the current placement tolerances: (Jason Smith SDDOT Poster)
- The results indicate the current tie bar placement tolerances may even be too strict
- Recommendations for future research:
  - Look into effects of multiple misalignments
  - See how the different misalignments perform under vertical loads or fatigue loading