

# **INSPECTION OF LOUISIANA TIMBER BRIDGES**

**By**

**Vijaya (VJ) Gopu, Ph.D., P.E**

**Professor and Edward G. Schlieder Endowed Chair**

**Dept. of Civil and Environmental Engineering**

**University of New Orleans**

**and**

**Associate Director – External Programs**

**Louisiana Transportation Research Center**

**International Conference on Timber Bridges, Las Vegas, NV,  
September 30, 2013**

# OUTLINE

- 1. Acknowledgements
- 2. Overview of timber bridge inventory statistics
- 3. Location of bridges inspected in Louisiana
- 4. Location within decay hazard zone(s)
- 5. Description of cluster bridges
- 6. Inspection methods
- 7. Bridge examples
- 8. Challenges
- 9. Summary

# Acknowledgements

Timber bridge inspections in Louisiana were conducted with the support of the following agencies and DOT staff members:


- Louisiana Department of Transportation and Development (LADOTD)
- Louisiana Transportation Research Center (LTRC)
- Steven Sibley, State Bridge Inspection Engineer
- Haylye Brown, Bridge Maintenance Engineer
- Keith Antee, Bridge Inspector

# Overview of Timber Bridge Inventory Statistics


- Only 4% (24,267) of the nation's bridge (NBI) are timber bridges. However, nearly 8% (46,530) of the bridges have timber elements in the superstructure.
- Louisiana has the second largest number (2,068) of timber bridges in the nation, about one in twelve of are in Louisiana.
- Nearly two thirds of Louisiana timber bridges are either structurally deficient (47%) or functionally obsolete (16.5%).



# Location of Bridges Selected for Study



# Location of Bridges in Decay Zone



# Details of Bridges Inspected in District 08

| Bridge No. | Decking      | Runners / Overlay | Stringers   | Piling | Length | Max Span | Num. Spans | Built |
|------------|--------------|-------------------|-------------|--------|--------|----------|------------|-------|
| 08-1       | Timber Plank | 7" Asphalt        | Sawn Lumber | Timber | 39     | 10       | 4          | 1967  |
| 08-2       | Timber Plank | 2" Gravel         | Sawn Lumber | Timber | 170    | 19       | 10         | 1977  |
| 08-3       | Timber Plank | 4" Asphalt        | Sawn Lumber | Timber | 58     | 19       | 3          | 1941  |
| 08-4       | Timber Plank | 4" Asphalt        | Sawn Lumber | Timber | 77     | 19       | 4          | 1941  |

# Details of Bridges Inspected in District 62

| Bridge No. | Decking      | Runners / Overlay | Stringers   | Piling | Length | Max Span | Num. Spans | Built |
|------------|--------------|-------------------|-------------|--------|--------|----------|------------|-------|
| 62-1       | Timber Plank | 2" Gravel         | Sawn Lumber | Timber | 31     | 15       | 2          | 1980  |
| 62-2       | Timber Plank | 5" Gravel         | Sawn Lumber | Timber | 154    | 19       | 8          | 1960  |
| 62-3       | Timber Plank | 5" Asphalt        | Sawn Lumber | Timber | 58     | 19       | 3          | 1968  |

# Details of Bridges Inspected in District 02

| Bridge No. | Decking      | Runners / Overlay | Stringers   | Piling | Length | Max Span | Num. Spans | Built |
|------------|--------------|-------------------|-------------|--------|--------|----------|------------|-------|
| 02-1       | Timber Plank | Runners           | Sawn Lumber | Timber | 57     | 15       | 4          | 1960  |
| 02-2       | Timber Plank | Runners           | Sawn Lumber | Timber | 53     | 15       | 4          | 1980  |



# Details of Bridges Inspected in District 61

| Bridge No. | Decking  | Runners / Overlay | Stringers   | Piling | Length | Max Span | Num. Spans | Built |
|------------|----------|-------------------|-------------|--------|--------|----------|------------|-------|
| 61-2       | Concrete | AC Overlay        | Sawn Lumber | Timber | 56     | 19       | 3          | 1974  |
| 61-1       | Concrete | AC Overlay        | Sawn Lumber | Timber | 96     | 20       | 5          | 1960  |

# INSPECTION METHODS

A five step procedure was adopted to conduct the bridge inspections and it involved the following:

- Labeling abutments, piers, girders, etc.
- Conducting initial visual assessment with hammer sounding
- Obtaining moisture content measurement in suspect & decay-prone areas
- Establishing baseline NDE data by collecting stress-wave & resistance micro-drilling data from areas of suspected sound wood;
- Investigating marked areas to measure the extent of internal deterioration by utilizing stress wave timer and resistance micro-drilling tool as needed.



**Bridge 08-4**





**Bridge 08-4**





**Bridge 08-4**





**Bridge 62-2, East Baton Rouge Parish**





**Bridge 62-2, Drains in  
Concrete Deck**





**Bridge 62-2, Side View**





**Bridge 62-2, View of Abutment**





**Bridge 62-2, View of Concrete Deck and Stringer Bracking**





**Bridge 62-2, Damaged Pile**






**Bridge 62-2, Pile Damage**






**Bridge 62-1, Decayed Pile**





**Bridge 62-2, Pile Damage**





**Bridge 62-2, Pile Damage**





**Bridge 62-1, Pile Damage**





2

## Bridge 62-1, Pile Damage





## Bridge 62-2, Pile Damage





**Bridge 62-2, Pile Damage**





**Bridge 62-1, Approach Road**





# Bridge 62-1



# Bridge 62-1






Crushing Cap  
above pile

Pile C

Bridge 62-1



# Bridge 62-1






**Bridge 62-1**



**Bridge 62-1**





**Bridge 08-4**





**Bridge 08-4**





**Bridge 08-4**





Bridge 08-4





Bridge 08-4





**Bridge 08-4**





**Bridge 08-4**





**Bridge 08-4**





**Bridge 08-4**



**Bridge 08-4**





**Bridge 08-4**





**Bridge 08-4**





**Bridge 08-4**





**Bridge 08-4**





**Bridge 08-4**





**Bridge 08-4**





**Bridge 08-4**



**Bridge 08-4**





**Bridge 08-4**

# CHALLENGES

- Some of the timber bridges originally selected for inspection could not be evaluated because of the high water level, currents and inadequate headroom to conduct an inspection from a boat. Substitutions were made to ensure the desired number of bridges were inspected.
- In long-span bridges it was extremely difficult, if not next to impossible, to use the resistance microdrill to assess the condition of the stringers and deck due to height of the pile bent. Climbing the braces provide access only to the pile cap and the stringers at the supports.



# CHALLENGES (contd.)

- Operating the microdrill at the top of the bent with one hand is nearly impossible without mobilizing Considerable equipment to gain access to the underside of long-span bridges with tall bents.
- Bridges with low clearance under the stringers offered a challenge also since it was difficult to operate the micro-drill in such small clearances.
- It was critical to have a three member team to conduct the investigation in order to manage the equipment and carry out the necessary documentation of the bridge inspection and assessment.

# SUMMARY

- The absence of a durable vapour barrier between the wood deck and the asphalt overlay allowed moisture to be trapped at the interface of the deck and the overlay and contribute to the decay and deterioration of the deck.
- Once the asphalt cracks -- which it does due to the flexibility of the timber deck -- moisture travels to the wood deck and gets trapped above the deck if there is no provision for the moisture to escape.
- It is critical that a flexible and reliable vapour barrier be placed between the timber deck and the asphalt paving to improve the service life of the deck.



# SUMMARY (contd.)

- The use of a water shedding groove in the timber deck board is important to avoid trapping of moisture.
- The use of timber abutments, while an easy alternative in some cases, should be avoided if possible to improve the service life of the overall bridge. The abutments can become a weak link in the bridge system.
- Timber pile deterioration in the zone of wetting and drying was observed in several bridges. Inexpensive treatment of piles sections in this zone with inorganic resins will significantly reduce pile deterioration which is the single most important reason for DOTs staying away from timber bridge systems.

# SUMMARY (contd.)

- The stringers in most of the bridges inspected were performing satisfactorily even after five decades and only occasional upgrading or strengthening was performed to repair damaged stringers or accommodate change in wheel loads.
- The key to performance of the timber bridge superstructure is the design and detail to keep it dry.
- A solution to improving the performance of the pile sub-structure is critical if timber is to be the material of choice for off-interstate highway bridges.



# *QUESTIONS ???*

