

LANGLEY COVERED BRIDGE REHABILITATION: Practical Solutions for Rehabilitation of a Historic Covered Bridge

National Covered Bridge Conference

Dayton, Ohio, June 7, 2013

by Thomas E. Nehil PE, Principal, Nehil•Sivak PC

414 S. Burdick, Suite 300, Kalamazoo MI 49007

tnehil@nehilsivak.com

NEHIL • SIVAK
CONSULTING STRUCTURAL ENGINEERS

Langley Covered Bridge Centreville, Michigan



OUTLINE

- ◆ Project background, history of bridge
- ◆ Assessment of rehabilitation needs, findings of structural analysis
- ◆ Rehabilitation construction process, lessons learned

BACKGROUND

- ◆ Project began 2005, completed 2009
- ◆ Project participants:
 - St Joseph County Road Commission
 - Preservation architect
 - Structural/preservation engineer
 - MDOT historian
 - Contractor

Significance of Langley Bridge

- ◆ Constructed 1887, timber Howe trusses
- ◆ One of four remaining historic covered bridges in Michigan
- ◆ One of the longest historic covered bridges in US
- ◆ Forms part of local identity
- ◆ Still in active use as county road

Project Location



The Langley bridge 1887



NEHIL • SIVAK
CONSULTING STRUCTURAL ENGINEERS

Raising the bridge for dam 1910



NEHIL • SIVAK
CONSULTING STRUCTURAL ENGINEERS

New causeway to connect bridge across floodplain



Later changes: deck, piers and abutments replaced 1950s



Roof raised and replaced



Sway bracing modifications



NEHIL • SIVAK
CONSULTING STRUCTURAL ENGINEERS

The fishing window




The Structure

◆ Heavy timber Howe through trusses




The Howe trusses here are the
historically significant feature




The Langley Bridge trusses

- ◆ Each truss 94 ft long, 16 ft tall, $h/L=6$
- ◆ 10 panels per span, 9'-2 3/4" each
- ◆ Diagonals slope 60



Trusses built up from sawed timber, three laminations at chords



Iron castings at nodes, tension rod bearing directly on chords



ASSESSING REHABILITATION NEEDS; FINDINGS OF STRUCTURAL ANALYSIS

Issues

- ◆ Bridge was posted for 3T load limit
- ◆ Load and speed limits regularly ignored
- ◆ Last major repairs and maintenance 1970's
- ◆ Previous modifications and repairs addressed functional requirements only, little regard for historic preservation

Recent Vehicle Impact



NEHIL • SIVAK
CONSULTING STRUCTURAL ENGINEERS

Issues with roof: framing and covering



Issues with siding: rot, lead paint peeling into the river



1950s steel deck framing,
corroded, lead paint peeling



Truss bottom chord reinforcing corroded, south span sagging



Low clearance an advantage during condition audit




Hands on, piece by piece



NEHIL • SIVAK
CONSULTING STRUCTURAL ENGINEERS

Rotting of bottom chord



**Raccoon
(Deceased)**

Rotting and crushing of compression diagonals



Crushing of tension rod bearings, at top chord...



And bottom





Purpose and Need: Defining the Loads

- ◆ We recommended public meetings held to discuss conversion to pedestrian and bicycle use only
- ◆ That idea not endorsed by community
- ◆ Community wanted to maintain crossing over river as a county road

Loads

- ◆ Modern loads per AASHTO vs horse-drawn carriages and wagons: 30,000# vs 7,000#



Structural analysis to assess repair and strengthening needs

- ◆ We examined roof framing, deck framing, trusses, girders and substructure, no work below the waterline
- ◆ Want to discuss here three issues:
 - Tension capacity of bottom chords
 - Load transfer at castings
 - Role of counterbraces in Howe trusses


Findings

- ◆ Timbers stresses within reasonable limits for No. 1 white pine, though at high end
- ◆ Tension rods also well within allowable stresses, ok for fatigue


Findings (cont)

- ◆ Max bottom chord tension on gross area of timbers appeared acceptable
- ◆ But tension chord members were spliced in original construction

Bottom chord splice locations



Fishplate detail




Bottom chord splices

- ◆ Evaluate tension on net area and shear parallel to grain in the timbers and fishplates, and compression on the bearing surfaces
- ◆ To support wagon loads, need 13,000# of load transfer through each fishplate if we rely on them alone to do the job


Assessing bottom chord tension capacity

- ◆ Per current code limits on bearing stress, bottom chord fishplate capacity is 5,200#, not adequate even to carry self weight of bridge
- ◆ Might then assume all tension carried by remaining two laminations (ref S. Patrick Sparks, APT Journal 2005), but they too are spliced
- ◆ Need to consider development of tension capacity of bottom chord as a whole, all three laminations


The weak links



Fishplates, keys, bolts acting



Fishplates, keys, bolts acting




Tension capacity using keys and fishplates


- ◆ Four bearing surfaces and one or two bolts in single shear at critical path
- ◆ Total capacity = 26,000 # per current NDS, including C_d and $0.75 F'_c$ limit
- ◆ (or 33,000# per pre-2001 NDS)
- ◆ Acceptable for wagon loads, not H15 on trusses with deteriorated and cobbled chords

Bottom chord strengthening

- ◆ Steel channels each side of each chord, hidden by siding
- ◆ Provided good bearing for deck beams and tension rods



Bolting pattern to develop tension in steel channels, not to splice wood lams



Load paths at castings

- ◆ Max vertical = 31 k, $f_c = 200$ psi (wagons)
- ◆ Max horizontal component = 18 k
- ◆ $f_{c//}$ on lug bearing surface = 1950 psi! but $F'_{c//}$ for EWP SSP&T = 834 psi



Force transfer at castings

- ◆ In recent times, max horizontal load carried may have been = 28k, so $f_{c//} = 3000$ psi
- ◆ Tension rods don't bear on wood, no dowel bearing to help out
- ◆ Friction?
- ◆ Is C_D of 1.15 too conservative?
- ◆ Confined $f'_{c//} = 3000$ psi, » 800 psi?

No action taken

- ◆ Had supported higher loads in the past without damage
- ◆ Ductile failure mode

THE REPAIR PROCESS



NEHIL • SIVAK
CONSULTING STRUCTURAL ENGINEERS

After lead abatement



Braced internally



Accessing the exterior



Replaced all tension rods and bearing plates



Repaired bottom chord bearing



Replaced and supplemented tension chord reinforcing



Spacers between wood and steel to promote durability





Compression diagonals at fishing window



NEHIL • SIVAK
CONSULTING STRUCTURAL ENGINEERS


Compression diagonal repairs



Reused timber washers



Maintenance painting of steel





NEHIL • SIVAK
CONSULTING STRUCTURAL ENGINEERS

Completed 2009




NEHIL • SIVAK
CONSULTING STRUCTURAL ENGINEERS


Sag didn't get removed




How to camber a Howe



Effect of tightening rods alone



Function of the counter braces?



- ◆ Was prestressing the original concept? Can it practically be maintained?
- ◆ We found almost all to be loose; they don't brace the compression diagonals out of plane
- ◆ Assembly requirement only?

Overall Satisfaction



NEHIL • SIVAK

CONSULTING STRUCTURAL ENGINEERS

