

Concrete Pavement Preservation Fundamentals



**National Concrete Pavement Technology Center
Iowa's Lunch-Hour Workshop
In cooperation with the Iowa DOT
and the Iowa Concrete Paving Association**




Investment



Protect the Investment
Review your Pavements
Plan for Preservation
Do it Correctly



Service Life



Maintenance vs. Preservation

Preventative Maintenance

- Maintain (or improve) the condition of the transportation system to a functional state of operation¹
- Part of asset management (routine & preventive maintenance)¹
- Applied to structurally sound pavements with significant remaining life


Preservation

- Work planned & performed to improve or sustain the condition of the transportation facility to a good condition¹ (keep good roads good)
- Generally do not add capacity or structural value, but restore the overall condition¹
- Extending life and restoring functional condition
- Collection of maintenance and minor rehabilitation



Maintenance vs. Preservation

Extend performance with proper Materials, Design & Construction



Trigger/Limit Values for Preservation (JPCP)

Start Programming



Performance Indicator	Trigger Value	Limit Value	Repair
Trans. Cracking	1.5-2.5% of slabs cracked	5-15% of slabs cracked	Partial, Full, Dowel Bar Repairs
Joint Deterioration	2.0-4.0% of joints	15-20% of joints	Partial-Depth Repair
Joint Faulting	1/8 inch	3/8 – 1/2 inches*	Dowel Bar Retrofit
Roughness	90 in/mi	170 in/mi*	Diamond Grinding




Treatment Performance Life


Treatment	Expected Performance (Treatment Life), Years
* Concrete joint resealing	8 - 15
* Concrete crack sealing	8 - 15
Diamond grinding	8 to 15
Diamond grooving	10 to 15
* Partial-depth concrete patching	12 - 20
* Full-depth concrete patching	15 - 25
* Dowel bar retrofit	15 - 20



Q3: Full Depth Repairs: What is your Agency's expected life of full depth repair?




Q5: Partial Depth Repairs: What is your Agency's experience doing partial depth repairs?




2017 Survey


Q7: Partial Depth Repairs: What is your Agency's expected life of partial depth repair?



Q9: Dowel Bar Retrofits: Does your Agency have any experience doing dowel bar retrofit repairs?



Q10: Dowel Bar Retrofits: What is your Agency's expected life of dowel bar retrofit repair?



Concrete Pavement Preservation Guide 2014



September 2014

Second Edition


CONCRETE PAVEMENT PRESERVATION GUIDE



- Contains 12 Chapters on Preservation Techniques
- Focus on Repair Techniques (How to do it)

Distress Assessments & Solutions

DIVISION 1 – FULL DEPTH CONCRETE PAVEMENTS



- Surface Defects
- Surface Delamination
- Material Related Cracks
- Transverse & Diagonal Cracking
- Longitudinal Cracking
- Corner Cracking
- Spalling
- Faulting
- Joint Warping and Curling
- Blowups
- Settlement and Heaves
- Subgrades & Base Support Conditions
- CRCP

Google:
CP Tech Center
Distress Manual
(pdf & ePub)

DIVISION 2 – CONCRETE OVERLAYS

- Concrete Overlays, BCOA, BCOC, UBCOA, UBCOC
- Laboratory & Field Testing

Full Depth Pavements

Ch 2. Surface Defects



Ch 3. Surface Delamination



Ch 4. Material-Related Cracks



Ch 5. Transverse/Diagonal Cracking



Full Depth Pavements

Ch 6. Longitudinal Cracking



Ch 7. Corner Cracking



Ch 8. Spalling



Chapter 9. Faulting



Full Depth Pavements

Ch 10. Joint Curling and Warping



Ch 11. Blowups



Ch 12. Subgrades and Base Support



Ch 13. CRCP




CHAPTER 14. INTRODUCTION TO DIVISION 2: CONCRETE OVERLAYS

This chapter will help quickly identify where in Division 2 of this manual you can find more detailed guidance on distresses in concrete overlays (causes and solutions). A brief overview of each chapter is provided along with a description of the overlay type being addressed


Concrete Overlay Distress Manual

Chapters


Ch 15. Bonded Concrete Overlay on Asphalt (BCOA)




Ch 16 Bonded Concrete Overlay on Concrete (BCOC)



Ch 17. Unbonded Concrete Overlay on Asphalt (UBCOA)



Ch 18. Unbonded Concrete Overlay on Concrete (UBCOC)



Ch. 15 Concrete Overlay on Asphalt (BCOA)

**Interior Structure/
Unbonded Cracks**



**Longitudinal lane-shoulder
joint spall due to shoulder
heave**



**Compression-transverse
joint due to slab expansion &
adjacent joints not opening**



Transverse joint faulting



Panel migration/slippage



**Mult. Longitudinal
cracking in wheel path**



Ch 16. BONDED CONCRETE OVERLAY ON CONCRETE (BCOC)

**Reflective crack over
transverse crack**



**Multiple panel cracks near
panel end due to debonding**



**Longitudinal crack-overlay
fatigue after debonding**



**Late sawing/or saw cut not directly
over existing joint/crack**



**Wheel path cracking-debond
& fatigue cracking of overlay**



**Reflective crack-not cutting
a joint over existing crack**




Ch. 17 UNBONDED CONCRETE OVERLAY ON ASPHALT (UBCOA)

Longitudinal cracking in wheel path with tied & widened shoulders



Faulting & panel movement of UBCOA due to deformation of the underlying HMA



Diagonal longitudinal crack over widened section



Cracking- misaligned dowels; paint marks dowel basket



Mid-panel cracking



Blowups



Ch 18 UNBONDED CONCRETE OVERLAY ON CONCRETE (UBCOC)

Longitudinal cracking in wheel path with tied & widened shoulders (UBCOC)



Transverse joint faulting of UBCOC



Longitudinal cracking in wheel path in UBCOC




Transverse reflective cracking of UBCOC



UBOC Mid-panel cracking



Cracking due to misaligned dowels, (yellow oval shows the exposed end of dowel)



COMMON DISTRESS TYPES

Longitudinal and Transverse Cracking – Causes and Prevention

Causes

Excessive slab length

Late sawing

Inadequate saw depth

Non-Uniform support
volume changes

Traffic loading

Prevention

Follow guidelines, saw to
adequate depth

Maximize sawing window,
increase labor/equip forces

Check blades, saw to T/4
on transverse joints (T/3 on longitudinal
and CD joints)

Uniform drainage, compact & subgrade
soils, chemically stabilize
subgrade if needed

Use proper thickness, keep
construction traffic away
from edges



Recommended Repairs for PCC Cracking


Defect	Orientation	Location	Description	Dowelled/Undowelled Transverse Joints	Recommended Repair	
Plastic Shrinkage	Any	Anywhere	Partial-depth and more than 0.007 in. wide	Either	Do nothing	
Uncontrolled Crack	Transverse	Mid-Panel	Full-Depth	Undowelled	Saw/route and seal crack	
				Dowelled	Full-Depth Repair or LTR ^a	
Uncontrolled Crack	Transverse	Crosses or ends at transverse joint	Full-Depth	Undowelled	Saw & seal crack; Epoxy sawed joint if uncracked	
				Dowelled	Full-Depth Repair or If crack jumps from sawcut to edge of slab within 3 feet of edge of slab, stop sawcut, saw & seal crack	
Uncontrolled Crack	Transverse	Parallel to & within 5 ft. of joint	Full-Depth	Undowelled	Saw and seal crack Seal joint	
				Dowelled	Full-Depth repair to replace crack and joint	
Spalled sawcut or uncontrolled crack	Transverse	Anywhere	Spalling; more than 3.0 in. wide	Either	Partial-Depth Repair	
Uncontrolled Crack	Longitudinal	Relatively parallel to & within 1 ft. of joint; May cross or end at longitudinal joint	Full-Depth	Either	Saw/route & seal the crack or cross-stitch the crack Epoxy sawed joint if uncracked	
Uncontrolled Crack	Longitudinal	Relatively parallel to & within wheel path; 1 - 5 ft. from joint	Full-Depth, hairline, or spalled	Either	Remove and replace panel or cross-stitch crack	
Uncontrolled Crack	Longitudinal	Relatively parallel to & further than 5 ft. from a longitudinal joint or edge	Full-Depth	Either	Cross-stitch crack	
Spalled sawcut or uncontrolled crack	Longitudinal	Anywhere	Spalled	Either	Partial-Depth Repair	
Uncontrolled Crack	Diagonal	Anywhere	Full-Depth	Either	Full-Depth Repair	
Uncontrolled Crack	Multiple per panel	Anywhere	Two or more full depth cracks dividing panel into 3 or more pieces	Either	Remove and replace panel	

Spalling - Causes

Distress	Category	Description
Spalling (Material or Chemical)	Heavy application of Magnesium & Calcium Chlorides	Deicing chemicals react with Calcium Hydroxide (CH) causing flaking of hardened paste
	Freeze Thaw Damage	Damage to the paste of the concrete from: <ul style="list-style-type: none"> • Poor air entrainment system • Saturated concrete joints/cracks • Chemical breakdown of the concrete from calcium and magnesium chloride (Calcium Oxychlorides)
	Thermal Expansion	High coefficient of thermal expansion (CTE) of the aggregate results in higher compressive stresses at the joint or crack.
Spalling (Physical)	Infiltration	Infiltration of incompressibles into poorly sealed or unsealed joints.
	Compression Shear	Compression shear from deflection of the slab, lack of load transfer, or lack of subgrade support
	Chipping/Fraying	Early sawing of the joint which chips or frays the edges of the joint.
	Moving Dowels	Dowel bar movement from misaligned dowels.



Joint Deterioration/Spalling



Air Distribution



How do we get low permeability?

Use SCMs to tie up CH

Cement

+

=



C-S-H

Water

+

SCM + Water + CH = more C-S-H

Calcium silicate hydrate (C-S-H) Calcium hydroxide (CH)



COMMON REPAIR METHODS


Partial-Depth Repair

Key Factors for Success


- Proper selection of candidate projects
- Proper material selection
- Identification of repair boundaries
- Use of joint/crack reformers
- Achieving good bond
- Proper placement and curing




Partial-Depth Repair




**PCC PATCH
ACROSS JOINT**




**SECTION A-A
(Option 1: Sawed Edges)**



**SECTION A-A
(Option 2: Milled Edges)**




**PCC PATCH
ABUTTING JOINT**



SECTION B-B

- ① Vertical saw cut (typical). Apply tack coat to sides and bottom.
- ② Taper the sides of the removal area 30 to 60 degrees from vertical. Apply cement grout to sides and bottom.
- ③ Saw and seal existing joint.
- ④ Extend patch limits at least 3 inches beyond distressed area.
- ⑤ When milled removal is allowed, sawed vertical edges are not required. Apply cement grout to milled area.



HMA PATCH

Partial Depth Repairs

SUDAS & Iowa DOT

- SUDAS (7040) requires compression relief material
- Iowa DOT (2530) allows compression relief boards or sawcutting for patches greater than 6'
- Iowa DOT (2530)
 - Partial Depth Finish Patches < 6' long
 - Partial Depth PCC Joint and Crack Repair Patches $\geq 6'$



Partial-Depth Repair Steps

1. Sounding



2. Marking Removal



3. Removal






4. Sand & Air Blast



Partial-Depth Repair Steps

5. Compression relief
6. Grout/Epoxy
7. Patch (Grout edge)
8. Curing
9. Joint seal




Partial-Depth Repair Removal Sawing / Jackhammers


- Small to medium walk-behind saw for perimeter cuts
 - Maneuverability
 - Positioning on paint marks
- Select light-weight hammer
 - 15 to 30 pound
 - More control
 - Less fatigue
- Use chisel or narrow spade bit for removal




Partial-Depth Repair Removal Milling




V Head




Tapered Head



Rounded Head



Vertical Head



High Flow Skid Steer



18K-lb Milling Machine



18K-lb Milling Machine



18K-lb Milling Machine

Partial Depth Repair (Over-depth Repairs)

- SUDAS: pay 2 x cost of partial depth repair for full depth repair
- Iowa DOT: pay for over-depth patches area calculated at mid depth of patch in addition to partial depth quantity



Full-Depth Repair

Key Factors for Success



- Removal (4' min.)
- Dowel bar holes (grout or epoxy)
- Cleaning holes
- Proper material selection
- Proper placement and curing



Figure 6.12. Example of gang drill used for dowel bar installation




Full Depth Repairs - Construction




Full-Depth Repair


GUTTERLINE JOINTING



ONE PANEL WIDTH PATCH WITH OPPOSING JOINT




ONE PANEL WIDTH PATCH NO OPPOSING JOINT




FULL ROADWAY WIDTH PATCH

THIRD POINT JOINTING


①




OUTSIDE PANEL PATCH WITH OPPOSING JOINT




OUTSIDE PANEL PATCH NO OPPOSING JOINT



FULL ROADWAY WIDTH PATCH




CENTER PANEL PATCH NO OPPOSING JOINT



ADJACENT PANELS PATCH


- ① Patches on roadways with quarter point jointing will be similar to third point jointing details.
- ② Minimum distance between existing joint and patch is 6 feet. If distance is less than 6 feet, extend patch to existing joint.
- ③ If subgrade or subbase material is required below patch, bring material to a level 2 inches below bottom of existing pavement.

LONGITUDINAL SECTION THRU PCC PATCH



③


FIGURE 7040.101 SHEET 1 OF 1

	REVISION	
	2	10-17-17
	7040.101	
	SHEET 1 of 1	
SUDAS Standard Specifications		
FULL DEPTH PCC PATCHES LESS THAN OR EQUAL TO 15' LONG		


Iowa DOT: Full Depth Finish Patches By Area & By Area 50'+(SY) and By Count (Each)
SUDAS: By Area (SY)

Full-Depth Repair

GUTTERLINE JOINTING




ONE PANEL WIDTH PATCH




FULL ROADWAY WIDTH PATCH


THIRD POINT JOINTING ①



OUTSIDE PANEL PATCH




CENTER PANEL PATCH



FULL ROADWAY

- ① Patches on roadways with quarter point jointing will be similar to third point jointing details.
- ② Minimum distance between existing joint and patch is 6 feet. If distance is less than 6 feet, extend patch to existing joint.
- ③ Match existing joint type and locations.
- ④ 'C' joint unless 'CD' joint is specified.
- ⑤ If existing joint spacing is greater than 20 feet, add a 'CT' joint at mid-panel.
- ⑥ If subgrade or subbase material is required below patch, bring material to a level 2 inches below bottom of existing pavement.

LONGITUDINAL SECTION THRU PCC PATCH





	REVISION
3	10-17-17
SUDAS 7040.102 SHEET 1 of 1	
SUDAS Standard Specifications	
FULL DEPTH PCC PATCHES GREATER THAN 15' LONG	

FIGURE 7040.102
SHE

3.02 FULL DEPTH PATCHING (Continued)

2. **Tie Bars and Dowel Bars:** Comply with Section 7010 and the figures in Sections 7010 and 7040.
 - a. When there is a common line between two adjacent patches, a bent bar may be placed in a keyway and later straightened.
 - b. Coat dowel bars extending into the patch area with a bond breaker. Do not coat tie bars.



Full-Depth Repair - Opening

Table 6.6. Minimum Opening Strengths for FDRs (ACPA 2006)

Slab Thickness, mm (in.)	Strength for Opening to Traffic, MPa (lbf/in. ²)			
	Repair Length <3 m (10 ft)		Slab Replacements	
	Compressive	3 rd -Point Flexural	Compressive	3 rd -Point Flexural
150 (6.0)	20.7 (3000)	3.4 (490)	24.8 (3600)	3.7 (540)
175 (7.0)	16.5 (2400)	2.6 (370)	18.6 (2700)	2.8 (410)
200 (8.0)	14.8 (2150)	2.3 (340)	14.8 (2150)	2.3 (340)
225 (9.0)	13.8 (2000)	1.9 (275)	13.8 (2000)	2.1 (300)
250+ (10.0+)	13.8 (2000)	1.7 (250)	13.8 (2000)	2.1 (300)

Concrete Pavement Preservation Guide, Second Edition

Table 7010.01: Minimum Age and Tested Strength of Pavement Before Opening

Class of Mix	Type of Cement	Minimum Age For Opening ¹	Minimum Compressive Strength (psi)	Minimum Flexural Strength Center Point (psi)
C	Type I	7 Days ²	3,000	500
M	Type I	48 Hours	3,000	500

¹ Opening without testing only allowed upon approval of Engineer

² Five calendar days for concrete 9 inches thick or more.

Note: Maturity Testing is not required for FDR

SUDAS Standard Specifications



Dowel Bar Retrofit

- Restores load transfer
- Reduces probability of pumping, faulting, and corner breaks
- Improves long-term rideability
- Increases service life




Dowel Bar Retrofit

- Need compressible insert
- 3 bars per wheel path, 6 bars per lane, 12" spacing
- 14" min. length

Pavement Thickness (in.)	Dowel Diameter (in.)
8	1.0
8 to 9.5	1.25
≥ 10 "	1.5




Dowel Bar Retrofit



- ① Extend concrete patch material 1/8" above existing concrete surface for projects to be diamond ground; construct flush if diamond grinding is not required.
- ② Sawcut joint width 3/16" min to 5/16" max. Saw after concrete patch material has set.


FIGURE 7040.106

SHEET 1 OF 1

	REVISION	
	New	10-17-17
	7040.106	
SHEET 1 of 1		
SUDAS Standard Specifications		
DOWEL BAR RETROFIT		

Case Study – NW State St, Ankeny

ITEM NO.	SUDAS NO.	ITEM	UNIT	TOTAL QTY	AS-BUILT QTY
DIVISION 7		STREETS AND RELATED WORK			
7.01	7040-1.08-C	Partial Depth Patches, PCC	SF	1,355	
7.02	7040-1.08-D	Crack and Joint Cleaning and Filling, Hot Pour	LF	1,545	
DIVISION 8		TRAFFIC CONTROL			
8.01	8030-108-A-O	Temporary Traffic Control	LS	1	
8.02	Special	Portable Dynamic Message Signs (PDMS)	C DAY	5	
DIVISION 11		MISCELLANEOUS			
11.01	11,020-1.08-A	Mobilization	LS	1	



Case Study – NW State St, Ankeny



Case Study – NW State St, Ankeny



Case Study – NW State St, Ankeny



CASE STUDY – Asbury Rd, Dubuque

- CONSTRUCTED IN 1991, 0.50 MILE IN LENGTH
- ROADWAY WIDTH OF 41' BOC , 8" PCC NO DOWELS
- ADT = 7,300 - 7,700
- DOWEL BAR RETROFIT, FULL DEPTH REPAIR, DIAMOND GRINDING AND CLEAN JOINTS / SEAL
- FIRST OF ITS KIND FOR THE CITY
- MARCH 5, 2015, ESTIMATE: \$334,510
- 3 BIDS: \$317,620 - \$347,500
- 45 WORKING DAY CONTRACT
- ❖ FAVORABLE BID - UNIT PRICES ALLOWED CITY TO ADD ADDITIONAL REHAB TO CENTER TURN LANE, ADDITIONAL FULL DEPTH REPAIRS, AND JOINT SEALING



CASE STUDY – Asbury Rd, Dubuque



CASE STUDY – Asbury Rd, Dubuque



CASE STUDY – Asbury Rd, Dubuque



CASE STUDY – Asbury Rd, Dubuque

DIAMOND GRINDING

- SUDAS SPECIFICATION FOR RIDEABILITY - 22 INCHES/MILE
- WESTBOUND **BEFORE** = 42.96 (INCHES/MILE)
 - ✓ WESTBOUND **AFTER** = 12.36 (INCHES/MILE)
- EASTBOUND **BEFORE** = 53.33 (INCHES/MILE)
 - ✓ EASTBOUND **AFTER** = 10.61 (INCHES/MILE)
- CENTER TURN LANE **BEFORE** = 37.71 (INCHES/MILE)
 - ✓ CENTER TURN LANE **AFTER** GRINDING = 13.38 (INCHES/MILE)



CASE STUDY – Asbury Rd, Dubuque

COMPLETED PROJECT - DETAILS

- PROJECT COMPLETION: 29 WORKING DAYS
45 DAY CONTRACT
- FINAL CONSTRUCTION COST: \$354,822 \$31 / SY
- TOTAL PROJECT COST: \$400,791 \$35 / SY
INCLUDES: DESIGN, CONSTRUCTION, INSPECTION
- DOWEL BARS INSTALLED: 3,300
- FULL DEPTH PATCHES, PCC: 350 SY
- DIAMOND GRINDING: 11,600 SY
- TRAFFIC CONTROL: \$37,000



CASE STUDY – West Des Moines

Investigation



Design

- Plans
- Standard Specification
- Standard detail



Construction



Credit: Jeff Nash, City of West Des Moines

CASE STUDY – US 30, Denison





Pavement Condition

- Joint Spalling
- Corner cracks
- Low friction
- Previous patches



Patching & Dowel bar Retrofit

CASE STUDY – US 30, Denison



Dowel bar retrofit and diamond grinding

CASE STUDY – US 30, Denison



- Previous IRI – 277 inches/mile (2017)
- New IRI – 116.7 inches/mile
- Previous PCI – 18 (very poor)
- Estimated new PCI – 87 (good)

Table 12.3. Concrete Pavement Preservation Treatments Based on Distress (adapted from Hall et al. [2001]).]

Concrete Pavement Preservation Treatment												
Distress	Slab Stabilization	Slab Jacking	Partial-Depth Repair	FDR	Retrofitted Edgedrains	DBR	Cross Stitching/Slot Stitching	Diamond Grinding	Diamond Grooving	Joint Resealing	Crack Sealing	Thin Concrete Overlay
Corner breaks			✓	✓							✓ ^a	
Linear cracking				✓			✓ ^b				✓ ^a	
Punchouts				✓								
D-cracking				✓ ^c								✓ ^c
Alkali-aggregate reaction				✓ ^c								✓ ^c
Map cracking, crazing, scaling			✓									✓
Joint seal damage										✓		
Joint spalling			✓	✓								✓
Blowup				✓								
Pumping	✓				✓	✓	✓					
Faulting						✓		✓				✓
Bumps, settlements, heaves		✓		✓				✓				✓
Polishing/low friction								✓	✓			✓

Bid Prices

- Patch, Partial Depth Repair, PCC: \$25-30/SF
- Patch, Full depth Repair: \$100-130/ SY
- Dowel Bar Retrofit: \$35-\$40 EA
- Partial Depth PCC Joint and Crack Repair Patches- \$35/ LF
- Pavement Surface Repair (Grind Limestone): \$3-4/SY
- Pavement Surface Repair (Grind Gravel): \$5-\$6/SY
(Slurry Management will add \$)
- Crack & Joint Clean & Fill: \$1.00 - \$1.50 per foot
- Sealer Material: \$1 per pound (6500-7000 lbs per mile)
- Mobilization: (5-8%) Varies by project



THANK YOU!

**Representing the National
Concrete Pavement
Technology Center**

